

FJS Security Project - Bug #22

SNMP: The two RSS switches has not been configured as SNMPv3

04/04/2019 11:27 AM - admin

Status:	Reserved	Start date:	04/04/2019
Priority:	Minor		
Assignee:	mdj		
Project:		Sender:	
Product:		External Reference:	
Observer:		Validation version:	
Observation Phase:		State justification:	
Visibility:	External	Additional info.:	
Scope:		Delivered version:	
Site:			
Description			
The two RSS switches has not been configured as SNMPv3, due to it cased the label ring1 ring2 turn to red in SRV display.			

History

#1 - 05/23/2019 11:18 AM - mdj

admin wrote:

The two RSS switches has not been configured as SNMPv3, due to it cased the label ring1 ring2 turn to red in SRV display.

since we cannot get the value of OID with snmpwalk v3 which we had used with snmp v1, so we suggest visit the status of RM on RSS switch by telnet, we created one script "telnet-switch.sh" and modified the script "check_by_snmp_eqt_status.sh",

steps:

1: copy these two files to the /home/adacs/ADACS_RT/com_cmd/ on cct1 and cct2