

FJS Security Project - Bug #38

Hivision: DGS WKS1 connection line is removed when reload the hivision config file or reboot

06/05/2019 03:28 PM - hwyang

Status:	Reserved	Start date:	06/05/2019
Priority:	Major		
Assignee:	mdj		
Project:		Sender:	
Product:		External Reference:	
Observer:		Validation version:	
Observation Phase:		State justification:	
Visibility:	Internal	Additional info.:	
Scope:		Delivered version:	
Site:			
Description			
Hivision: DGS WKS1 connection line is removed when reload the hivision config file or reboot			

History

#1 - 06/11/2019 02:40 PM - mdj

hwyang wrote:

Hivision: DGS WKS1 connection line is removed when reload the hivision config file or reboot

remove the check of of snmpv3 reachability in protocol, the dgs-wks1 is ok when load the ihp configuration file or reboot. but the dgs-wks2's line will be moved when load the ihp file, but it is ok when reboot the dgs-wks2.