

FJS Security Project - Issues

#	Tracker	Priority	Subject	Status	Assignee	Updated
38	Bug	Major	Hivision: DGS WKS1 connection line is removed when reload the hivision config file or reboot	Reserved	mdj	06/11/2019 02:40 PM
36	Bug	Minor	SAS: Only one screen is locked when use lock screen function	Reserved	mdj	05/31/2019 10:39 AM
34	Bug	Major	Hivision: all the icon keep red when load the hivision data file	Reserved	mdj	06/03/2019 03:01 PM
33	Bug	Minor	Printer: door open staus is not monitored for back door.	Reserved	mdj	06/03/2019 03:07 PM
32	Bug	Minor	SNMP: The BW printer status don't update when status change	Reserved	mdj	06/03/2019 03:10 PM
22	Bug	Minor	SNMP: The two RSS switches has not been configured as SNMPv3	Reserved	mdj	05/23/2019 11:18 AM
21	Bug	Major	Hivision: the hivision server or workstion icon will be removed when refresh or stop one ws or server.	Reserved	mdj	06/03/2019 03:01 PM
18	Bug	Major	SNMP: SAS1/2 SNMP V3 is removed	Reserved	mdj	05/23/2019 05:47 PM
17	Bug	Major	SNMP: the printer manage by different SAS	Reserved	mdj	05/23/2019 05:49 PM
16	Bug	Minor	SNMP: The printer propertiy list is different with them with France deliver version	Reserved	mdj	05/23/2019 05:51 PM
15	Bug	Minor	SNMP: The printer icon is the same for color and BW printer.	Reserved	mdj	03/26/2019 06:03 PM
12	Bug	Major	SNMP: all the logs need updated	Reserved	mdj	05/27/2019 10:19 AM
11	Bug	Minor	Supervision: Printer status are not stable	Reserved	mdj	03/28/2019 03:03 PM