FJS Security Project - Bug #13

SNMP: switchboard should be updated to SNMPV3,

03/26/2019 11:45 AM - admin

Status: Validated Start date: 03/26/2019

Priority: Minor
Assignee: mdj

Project: Sender:

Product: External Reference:

Observer: Validation version:

Observation Phase: State justification:

Visibility: Internal Additional info.:

Scope: Delivered version:

Site:

Delivered version:

Description

SNMP: Switchboard should be updated to SNMPV3 and disable SNMPV1 and V2

YHW 20190530 Validated OK

Related issues:

Copied to Bug #14: SNMP: the property security of swith always display warning Validated 03/26/2019

History

#1 - 03/26/2019 11:47 AM - admin

- Assignee set to mdj

#2 - 03/26/2019 05:42 PM - admin

- Copied to Bug #14: SNMP: the property security of swith always display warning added

#3 - 05/24/2019 02:18 PM - mdj

admin wrote:

SNMP: Switchboard should be updated to SNMPV3 and disable SNMPV1 and V2

fixed

#4 - 06/03/2019 10:49 AM - hwyang

- Description updated
- Status changed from Reserved to Validated

11/07/2025 1/1